



DETROITTM
DEMAND PERFORMANCESM

18SP693 – EPA07/10 Fuel Rail Clamp Service Kit (P/N: A4720780335) for DD Platform-Three-Filter Fuel System Engines



Notice:

Every time a fuel rail clamp (P/N: A0009905707) or fuel rail clamp bolt (P/N: A4700780135) is replaced, ALL of service kit (P/N: A4720780335) will have to be installed. Failure to do so may result in damage to the camshaft housing.

KIT CONTENTS

Service kit (P/N: A4720780335) contains all of the necessary parts to replace all fuel rail clamps and fuel rail clamp bolts on an EPA07/10 DD13/15/16 engine.

Part No.	Qty.	Description
A4700780335	3	Fuel Rail Clamps
A0019901207	6	Fuel Rail Clamp Bolts
18SP693	1	Installation Instructions

Table 1 EPA07/10 Fuel Rail Clamp Service Kit (P/N: A4720780335)

Refer to Power Service Literature for detailed instructions on replacement of the fuel rail clamps and fuel rail clamp bolts.



13400 Outer Drive, West, Detroit, Michigan 48239-4001
Telephone: 313-592-5000
www.detroitdiesel.com

Specifications are subject to change without notice. Detroit Diesel Corporation is registered to ISO 9001:2001.
Copyright © 2013 Detroit Diesel Corporation. All rights reserved. Detroit Diesel Corporation is a Daimler company.

18SP693 0113 As technical advances continue, specifications will change. Printed in U.S.A.